




Step 1-make report in the structural level




Step 2 - setting up the report



Step 3 - choose the *.rdlc file, output file, program & destination folder



Step 4 - choose the source drawing file for the report



Step 5- report ready to generate

